

COES Graduate Certificates

Six Sigma Green Belt

Must earn an A or a B in each class.

1. INEN 5143 001 or V84 Statistical Analysis for Six Sigma (offered fall and spring quarters)
2. INEN 5663 001 or V84 Six Sigma and Quality Control (offered winter and summer quarters)

Lean

Must earn an A or a B in the class.

1. INEN 5113 001 or V84 Theory and Application of Lean Manufacturing and Management (offered fall and spring quarters)